M. A. R. 57 (Rule 116) **No. D** 58816

Measurement Book

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
		1 -	25.40	0.90	-	23.134	
		1 -	13.30	0.90	-	11.97	
		1 -	30.60	0.90	-	27.60	
		1 -	13.90	0.90	-	12.51	
		2 x 1	30.60	0.90	-	54.60	
		1 -	4.30	0.90	-	3.87	
	(3). Cross-Road ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ಶಿವಮೊಗ್ಗ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ	1 -	30.60	0.70	-	22.50	
	4). P.W.D. ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ	1 -	19.60	0.75	-	13.50	
	ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು	1 -	29.30	0.90	-	26.37	
		1 -	30.60	0.90	-	27.60	

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
		1	26.00	0.90	-	23.40	C&PC
		1	30.00	0.90	-	27.00	
		1	25.00	0.90	-	22.50	
		1	30.00	0.90	-	27.00	
		1	10.00	0.90	-	9.00	
		1	30.00	0.90	-	27.00	
		3	2.00	0.90	-	2.70	
		1	16.50	0.90	-	14.85	
		1	15.50	0.90	-	13.95	
					Total Rs	1071.60	m²
					Add Rs	1071.00	m²
					@	1720.00	m²

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಕಳ್ಳಿ ಉಪಕಛೇರಿ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್. ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಕಳ್ಳಿ ಉಪಕಛೇರಿ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್. ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

30/4/18

3/5/18

RS - 1842+20=00

Scanned by CamScanner

M. A. R. 57 (Rule 116) **No. D** 58817

Measurement Book

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions: Length	Dimensions: Breadth	Dimensions: Depth	Contents	Reference to last Measurement
1	2	3	4	5	6	7	8
						Total Rs	99,92,312-50

Certificate

(1) Certified that the contractor has Laddle done satisfactorily.

(2) The contractor has removed the debris from Work site.

(3) There is no any Depth materials issued to contractor.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

ಚಿಕ್ಕಬಳ್ಳಾಪುರ

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Scanned by CamScanner

M. A. R. 57 (Rule 116) **No. D** 58818

Measurement Book

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions			Contents	Reference to last Measurement
			Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Audited and admitted for Rs. 9992312=00 Passed by C... (..... ..... by ad[illegible] Accounts Officer Exec. Engineer [illegible] Division		9690532=00 — — 301780=00				

Scanned by CamScanner

M. A. R. 57 (Rule 116)
Measurement Book

58868

Serial No. 1st and final Bill

Name of work ..... 'Pre-measurement' From ..... To .....

Name of Contractor of nature of Agency..... Sri. Kumar B.J.

Date of commencement of work..... D.o. Records : 16-01-2018

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Name of work :. Development of secondary drains and tertiary drains at Ward no. 12, Shettyhalli Div. in Shettyhalli Sub-Division.						
	Estimated cost Rs 100.00 Lakh						
	JO Bud : 012-14-000040						
	Work ordered : EE/DD 20/128/2017-18. Dt. 18.12.2017.						

Scanned by CamScanner

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

58869

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions		Depth	Contents	Reference to last Measurement
			Length	Breadth			
1	2	3	4	5	6	7	8
	(c) - 2nd Cross Road. R/s	2×1	30.00	1.20	1.05	75.60	
		1	10.00	1.20	1.05	12.60	
	(d) - 2nd — " — R/s	2×1	30.00	1.20	1.05	75.60	
		1×1	19.00	1.20	1.05	23.94	
	(4 - 3rd — " — 4/s	2×1	30.00	1.05	1.05	66.15	
		1	[illegible]	1.05	1.05	22.05	
	ಸಹಾಯಕ [illegible] ಮುಖ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರು						
	[illegible] ಉಪಚಾರಾಗ, ದೇವಸಂದ್ರ [illegible] ಸ್ಥಳಯ	2×1	30.00	1.20	1.05	75.6	
	ಬೆಂಗಳೂರು ಮುಕಾನಗರ ಪಾಲಿಕೆ	1	25.00	1.20	1.05	25.20	
	P.W.D. ರಸ್ತೆ, ರಾಜರಾಜೇಶ್ವರಿನಗರ, ಬೆಂಗಳೂರು		30.00	1.20	1.05	226.80	

Scanned by CamScanner

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

58870

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions			Contents	Reference to last Measurement
			Length	Breadth	Depth		
1	2	3	4	5	6	7	8
		1	26.00	1.20	1.05	32.76	
		1	30.00	1.20	1.05	37.80	
		1	25.00	1.20	1.05	31.50	
		1	30.00	1.20	1.05	37.80	
		1	10.00	1.20	1.05	12.60	
		1	30.00	1.20	1.05	37.80	
		1	3.00	1.20	1.05	3.78	
		1	6.15	1.75	1.00	10.67	
		1	5.00	1.75	1.00	9.63	

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೆಟ್ಟಕಲ್ಲ ಉಪವಿಭಾಗ, ಧಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ವಸ್ತ್ರ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

ಸಂ.ಅ.ಇ.